

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 MG ZS

LUXURY TROPHY | 110,680 KM

VIN: LSJW74C98NZ053800

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	110680	Specs	Yes
Engine	1.3L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	LSJW74C98NZ053800		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Lane Departure Warning System	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Front Camera	✓
Side Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓

Airbag Passenger Front	✓	ABS	✓
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓		
Performance			
Hill Descent Control	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	Rear left door
Rear right door Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm	

Fenders Condition

Left Fender	Right Fender Right Fender: Paint Chip-off

Quarter Panels Condition

Left Quarter Panel Condition: Dent	Right Quarter Panel Condition: VIP Tag/ other sticker

Rear Bumper Condition

Rear Bumper Rear Bumper: Scuffing > 80mm, Chip< 8mm, Crack/ Misaligned

Hood Condition

Hood Bonnet: Scuffing > 50mm, Dent > 30mm

Roof Condition

Roof

Running Board Condition

Left Running Board	Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield Condition: Front Wiper blades need	Rear Windshield Wiper blade damaged

replacement

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top Fair Use Wear/Crack<5mm	!		

Rear View Mirror Condition

Left Hand Side Mirror Body: Minor mirror damage	!	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition Dry coolant mark - thermostat	!
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Brake Fluid

Front Brake Pad Thickness < 3mm

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Button Faded

Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure Warning Light

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Right DRL: Low Brightness

Fog Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Rear Entertainment

Power/ Manual Windows

Seat Heaters

Interiors & Luggage

Dashboard And Instrument Panel

Central Console

Steering Wheel

Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet Front Left Floor Mat: Smudge/Burn/Crack	!
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE