


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.




**2023 HONDA CITY**

**SPORT | 71,660 KM**

VIN: MAKGN269XP4100046

## Car highlights

### Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

### Cruise control

Cruise control to drive with ease & comfort

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 71660 | Specs | Yes |
| Engine | 1.5L | Option Type | Fully Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SEDAN | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Grey |
| Interior Trim | Partial Leather Trim | Number of Airbags | 6 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 2 Keys |
| VIN number | MAKGN269XP4100046 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Safety & Security | | | |
|---|---|---|---|
| Adaptive cruise control | ✓ | Lane Departure Warning System | ✓ |
| Navigation | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Side Camera | ✓ |
| Airbag Sides | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |

| | | | |
|---|---|---|---|
| ABS | ✓ | | |
| **Comfort & Convenience** | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Power Windows Rear | ✓ | | |
| **Exteriors** | | | |
| Fog Light Front | ✓ | Running Lights | ✓ |
| **Performance** | | | |
| Paddle Shift | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

Doors condition

Front right door
Panel: Low Visibility Dent < 30mm

Rear left door

Rear right door
Panel: Low Visual Dent < 30mm

Fenders Condition

Left Fender

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent

Rear Bumper Condition

Rear Bumper
Rear Bumper: Replaced, Fully Repainted, Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board
Condition: Scuffing > 80mm

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield

Rear Windshield

Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Boot Floor | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

| | |
|---|---|
| Cowl Top | ✓ |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |

| | |
|---|---|
| Grill Condition<br>Fully Repainted | ! |

Panel Condition

| | |
|---|---|
| Rear Trunk Panel | ✓ |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

Steering

| | |
|---|---|
| Steering wheel | ✓ |

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |

Suspension

| | |
|---|---|
| Shock Absorbers | ✓ |

## Electricals, Controls & Lights

Keys

| | |
|---|---|
| Master Key | ✓ |

Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | | |
| Power/ Manual Windows | ✓ | Memory Seats | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel | ✓ | Headliner | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <55% | LHS Rear Tyre | <90% |
| RHS Front Tyre | <90% | RHS Rear Tyre | <90% |
| Spare Tyre | <35% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE